

Fluktuacije displeja i promene mernih vrednosti

If the measuring circuit is not connected, the open input functions as an antenna due to its high input impedance, and causes in random measured values to appear at the display. High input impedance is necessary in order to increase accuracy and minimize measuring error.