

**METRAport 40S / VAG 1526 - Merenje faktora ispune (Duty Factor) očitava 0.0% kao izmerenu vrednost**

Zahtevi za signal koji se meri:

- Amplitude between 2 and 5 V
- Frequency between 100 Hz and 10 kHz
- No DC offset (if necessary decouple with a series connected, 10 to 20 nF capacitor)